

**Recall Quarterly Report****14V-262**

**Manufacturer Name :** Suzuki Motor of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 14V-262 /XA  
**Recall Subject :** Headlamp Switch or DRL Module Overheating  
**Owner Notification Beginning Date :** OCT 29, 2014  
**Owner Notification End Date:**



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 30, 2015	2015-1	184,244	15,738	6,740	822
1	JAN 26, 2015	2014-4	184,244	4,685	3,020	627

This Document Last Updated : MAY 04, 2015

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.