

**Recall Quarterly Report****14V-371**

**Manufacturer Name :** Terex South Dakota, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 14V-371 /SN611  
**Recall Subject :** PTO Pressure Switch Oil Leak may Result in Fire  
**Owner Notification Beginning Date :** SEP 15, 2014  
**Owner Notification End Date:**



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 27, 2015	2014-4	74	4	0	0
1	OCT 31, 2014	2014-3	74	4	0	0

This Document Last Updated : FEB 13, 2015

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.