

Recall Quarterly Report**14V-371**

Manufacturer Name : Terex South Dakota, Inc.
NHTSA Recall No. / MFR Recall No. : 14V-371 /SN611
Recall Subject : PTO Pressure Switch Oil Leak may Result in Fire
Owner Notification Beginning Date : SEP 15, 2014
Owner Notification End Date: SEP 15, 2014



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	JAN 27, 2016	2015-4	74	38	0	0
5	OCT 20, 2015	2015-3	74	24	0	0
4	JUL 28, 2015	2015-2	74	21	0	0
3	APR 30, 2015	2015-1	74	16	0	0
2	JAN 27, 2015	2014-4	74	4	0	0
1	OCT 31, 2014	2014-3	74	4	0	0

This Document Last Updated : FEB 08, 2016

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.