

**Recall Quarterly Report****14V-715****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**NHTSA Recall No. / MFR Recall No. :** 14V-715 /**Recall Subject :** Ball Joint may Detach from Left Lower Arm**Owner Notification Beginning Date :** DEC 12, 2014**Owner Notification End Date:**

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 27, 2016	2016-1	5,650	5,095	140	0
5	JAN 27, 2016	2015-4	5,650	5,006	0	0
4	OCT 30, 2015	2015-3	5,650	4,859	0	0
3	JUL 27, 2015	2015-2	5,650	4,622	0	0
2	APR 29, 2015	2015-1	5,650	4,143	0	0
1	JAN 30, 2015	2014-4	5,650	2,258	0	0

This Document Last Updated : MAY 12, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.