

# Recall Quarterly Report

# 14V-737

**Manufacturer Name :** Mack Trucks, Inc.

**NHTSA Recall No. / MFR Recall No. :** 14V-737 / SC0385

**Recall Subject :** Ball Socket may Detach from Tie Rod

**Owner Notification Beginning Date :** JAN 20, 2015

**Owner Notification End Date:**



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2        | JUL 08, 2015    | 2015-2         | 3,266             | 725            | 0                 | 0             |
| 1        | APR 09, 2015    | 2015-1         | 3,266             | 521            | 0                 | 0             |

This Document Last Updated : JUL 08, 2015

## Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.