

**Part 573 Safety Recall Report****14V-339****Manufacturer Name :** General Motors LLC**Submission Date :** OCT 01,2014**NHTSA Recall No. :** 14V-339**Manufacturer Recall No. :** 14356**Manufacturer Information :**

Manufacturer Name : General Motors LLC

Address : 30001 VAN DYKE

MAIL CODE 480-210-2V WARREN MI 48090

Company phone : 999

**Population :**

Number of potentially involved : 57,192

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 CHEVROLET SILVERADO HD

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

Descriptive Information : 2015 Chevrolet Silverado HD Crew - Crew LTZ -Ext and Regular

Production Dates : OCT 01, 2013 - SEP 20, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2015 GMC SIERRA HD

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Sierra HD - Crew - Crew Denali and Regular

Production Dates : SEP 30, 2013 - SEP 20, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

**Description of Defect :**

Description of the Defect : General Motors LLC (GM) is recalling certain model year 2015 Chevrolet Silverado 2500 and 3500 HD vehicles manufactured October 1, 2013 to June 6, 2014, and 2015 GMC Sierra 2500 and 3500 HD vehicles manufactured September 30, 2013, to June 6, 2014. The power steering hose clamp may disconnect from the power steering pump or gear, causing a loss of power steering fluid.

Description of the Safety Risk : A loss of power steering fluid could result in a loss of power steering assist and power brake assist, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : GM will notify owners, and dealers will inspect the vehicles to make sure the power steering hose clamps are properly secured, free of charge. The recall is expected to begin in early August 2014. Owners may contact GM customer service at 1-800-222-1020 (Chevrolet) or 1-800-462-8782 (GMC). GM's number for this recall is 14356.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUN 11, 2014 - JUN 11, 2014

Planned Owner Notification Date : AUG 31, 2014 - NR

\* NR - Not Reported