OMB Control No.: 2127-0004

Part 573 Safety Recall Report

14V-353

Manufacturer Name: Honda (American Honda Motor Co.)

Submission Date: NOV 03,2014 NHTSA Recall No.: 14V-353 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Honda (American Honda Motor Co.)

Address: 1919 Torrance Blvd.

Torrance CA 90501 Company phone : 310-783-2000

Population:

Number of potentially involved : 698,288 Estimated percentage with defect : NR

Vehicle Information:

Vehicle: 2003-2005 Honda Accord Sedan

Vehicle Type:

Body Style : 4-DOOR Power Train : NR

Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever

registered in California

Production Dates : JAN 14, 2003 - MAR 30, 2005

VIN (Vehicle Identification Number) Range

 $\begin: NR \\ \begin: NR \\ \begin : NR \\ \begin : NR \\ \begin : NR$

Vehicle: 2003-2005 Honda Civic Sedan

Vehicle Type:

Body Style : 4-DOOR Power Train : NR

Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever

registered in California

Production Dates: FEB 01, 2003 - JAN 20, 2005

VIN (Vehicle Identification Number) Range

Vehicle: 2003-2004 Honda Civic CNG Vehicle Type: Body Style: Power Train: CNG/LPG			
Descriptive Information : Certain model year Honda and Acura vehicles that were originally sold in, or ever registered in California			
Production Dates : FEB 21, 2003 - AUG 19, 2004			
VIN (Vehicle Identification Number) Range			
Begin: NR	End: NR	☐ Not sequential VINs	
Vehicle: 2003-2005 Honda Civic Hybrid Vehicle Type: Body Style: Power Train: HYBRID ELECTRIC Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever registered in California Production Dates: APR 25, 2003 - JAN 18, 2005			
VIN (Vehicle Identification Number) Range			
Begin: NR	End : NR	☐ Not sequential VINs	
Vehicle: 2003-2004 Honda Civic Coupe Vehicle Type: Body Style: 2-DOOR Power Train: NR Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever registered in California Production Dates: FEB 01, 2003 - AUG 25, 2004			
VIN (Vehicle Identification Number) Range			
Begin: NR	End: NR	☐ Not sequential VINs	
Vehicle: 2003-2005 Honda CR-V 2WD Vehicle Type: Body Style: Power Train: NR Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever registered in California Production Dates: APR 23, 2003 - OCT 29, 2004 VIN (Vehicle Identification Number) Range			
Begin: NR	End : NR	☐ Not sequential VINs	
20gm · IIIv	Liid . INIV		

Vehicle: 2005-2005 Acura RL Vehicle Type: Body Style: Power Train: NR Descriptive Information: Certain model year		originally sold in, or ever	
registered in California Production Dates : JUL 15, 2004 - OCT 08, 2004			
VIN (Vehicle Identification Number) Range			
Begin: NR	End: NR	☐ Not sequential VINs	
Vehicle: 2003-2004 Honda Element 2WD Vehicle Type: Body Style: Power Train: NR Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever registered in California Production Dates: FEB 03, 2003 - DEC 13, 2004			
VIN (Vehicle Identification Number) Range			
Begin: NR	End : NR	☐ Not sequential VINs	
Vehicle: 2003-2004 Honda Element 4WD Vehicle Type: LIGHT VEHICLES Body Style: Power Train: NR Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever registered in California Production Dates: FEB 03, 2003 - DEC 13, 2004			
VIN (Vehicle Identification Number) Range			
Begin: NR	End: NR	☐ Not sequential VINs	
Vehicle: 2003-2004 Honda Odyssey Vehicle Type: Body Style: VAN Power Train: NR Descriptive Information: Certain model year Honda and Acura vehicles that were originally sold in, or ever registered in California Production Dates: FEB 01, 2003 - AUG 13, 2004 VIN (Vehicle Identification Number) Range			
		Not so so so the LVING	
Begin: NR	End : NR	☐ Not sequential VINs	

Page 5

Description of Defect:

Description of the Defect: In certain vehicles that were originally sold, or ever registered in California and

equipped with Takata-brand air bag inflators. Upon deployment of the passenger

side frontal air bag, excessive internal pressure may cause the inflator to rupture.

Description of the Safety Risk: In the event of a crash necessitating deployment of the passenger side frontal

air bag, the inflator could rupture with metal fragments striking and potentially

seriously injuring the vehicle occupants.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

Supplier Identification:

Component Manufacturer

Name: TK Holdings, Inc.

Address: 888 16th Street NW

Suite 800 Washington DISTRICT OF COLUMBIA 20006

Country: United States

Chronology:

NR

Description of Remedy:

Description of Remedy Program: Honda will notify owners, and dealers will replace the inflators in all affected

vehicles, free of charge. The recall is expected to begin during August 2014.

Owners may contact Honda customer service at 1-800-999-1009.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production: NR

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: SEP 08, 2014 - NR

* NR - Not Reported