

**Part 573 Safety Recall Report****14V-392****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** OCT 26,2015**NHTSA Recall No. :** 14V-392**Manufacturer Recall No. :** P37**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

**Population :**

Number of potentially involved : 20,323

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 CHRYSLER 200

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Involved vehicle revision

Production Dates : MAY 21, 2014 - JUN 05, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 JEEP CHEROKEE

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : MAY 21, 2014 - JUN 05, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 RAM 1500

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : MAY 21, 2014 - JUN 05, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Chrysler Group LLC (Chrysler) is recalling certain model year 2014 Jeep Cherokee and Ram 1500 and 2015 Chrysler 200 vehicles. Due to an insufficient weld, the rear shocks may detach from the vehicle at one end and possibly damage other chassis components, the tire or result in reduced braking.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Damage to the tire or reduced braking increases the risk of a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Hitachi

Address : NR

NR

Country : NR

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Chrysler will notify owners, and dealers will inspect the rear shocks and replace any affected ones, free of charge. The recall is expected to begin in August 2014. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is P37.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported