

Part 573 Safety Recall Report**14V-452****Manufacturer Name :** Collins Bus Corporation**Submission Date :** AUG 26,2014**NHTSA Recall No. :** 14V-452**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Collins Bus Corporation

Address : P.O. Box 2946

Hutchinson KS 67504

Company phone : 9999

Population :

Number of potentially involved : 374

Estimated percentage with defect : 25

Vehicle Information :

Vehicle : 2014-2014 COLLINS DE500

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : NR

Production Dates : MAY 18, 2012 - MAY 30, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2013-2013 COLLINS DE500

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : MAY 18, 2012 - MAY 30, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2012-2012 COLLINS DE500

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : MAY 18, 2012 - MAY 30, 2014

Description of Defect :

Description of the Defect : Collins Bus Corporation (Collins) is recalling certain model years 2012-2014 DH500, DH516, DH516WR, DE500, and DE516WR school buses manufactured May 18, 2012 to May 30, 2014. The affected vehicles may experience the propane fuel line rubbing on the body mount bolt head. This can happen due to movement of the body and chassis causing interference between the propane line and the body mount bolt.

Description of the Safety Risk : The interference between the propane line and body mount bolt could cause failure of the propane system, increasing the risk of fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Collins will notify owners, and dealers will inspect and relocate the propane fuel line, free of charge. The recall is expected to begin July 31, 2014. Owners may contact Collins customer service at 1-800-533-1850.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JUL 31, 2014 - NR

* NR - Not Reported