

**Part 573 Safety Recall Report****14V-506****Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** SEP 15,2014**NHTSA Recall No. :** 14V-506**Manufacturer Recall No. :** 131**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152

605 W. Crystal Lake Rd. Forest City IA 50436

Company phone : 1-641-585-3535

**Population :**

Number of potentially involved : 57

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 WINNEBAGO ITASCA SUNSTAR

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : APR 26, 2014 - JUN 27, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2015 WINNEBAGO VISTA

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : 4/26/2014 - 6/27/2014

Production Dates : APR 01, 2014 - JUN 30, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

**Description of Defect :**

Description of the Defect : Winnebago Industries, Inc. (Winnebago) is recalling certain model year 2015 Vista, and Itasca Sunstar motorhomes manufactured April 26, 2014, to June 27, 2014. The affected vehicles may be missing a damper plate on the inside air conditioner shroud. This damper plate is to help prevent disruption of the range flame by air discharge from the roof air conditioner.

Description of the Safety Risk : If the range flame goes out and propane is still flowing, it can cause a fire in the presence of an ignition source.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

Winnebago Industries, Inc. identified a potential issue during an internal audit on June 30, 2014. On August 15, 2014 we concluded our evaluation. We have decided that a defect which relates to motor vehicle safety exists.

**Description of Remedy :**

Description of Remedy Program : Winnebago will notify owners, and dealers will remove the current diverter and replace it with a damper plate, free of charge. The recall is expected to begin in September 2014. Owners may contact Winnebago customer service at 1-800-537-1885. Winnebago's number for this recall is 131.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 05, 2014 - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported