

Part 573 Safety Recall Report**14V-512****Manufacturer Name :** Autocar Industries, LLC**Submission Date :** APR 17,2015**NHTSA Recall No. :** 14V-512**Manufacturer Recall No. :** T-1409**Manufacturer Information :**

Manufacturer Name : Autocar Industries, LLC

Address : 551 South Washington Street

Hagerstown IN 47346

Company phone : 765-489-5499

Population :

Number of potentially involved : 19

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 AUTOCAR XSPOTTER

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : NR

Production Dates : MAY 23, 2014 - JUN 13, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs

Vehicle : 2015-2015 Autocar Xpert

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Xpert

Production Dates : MAY 23, 2014 - JUL 19, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs**Description of Defect :**

Description of the Defect : Autocar Industries, LLC (Autocar) is recalling certain model year 2015 Xspotter and Xpert heavy duty trucks manufactured May 23, 2014, to July 19, 2014 equipped with certain model Fleetguard UFF-XT fuel filters part number FF63009, manufactured April 25, 2014, to June 29, 2014 installed on Cummins ISB, and ISL engines built April 28, 2014, to July 9, 2014. The bond on the filter shell and the

filter nut plate may fail, causing the shell to separate from the fuel filter nut plate causing the engine to stall without warning.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the engine stalls unexpectedly due to the shell separating from the fuel filter nut plate, it increases the risk of a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Cummins

Address : NR

FOREIGN STATES

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Cummins will notify owners for Autocar, and dealers will replace the fuel filter with a non-defective one, free of charge. The recall was expected to begin August 8, 2014. Owners may contact Autocar customer service at 1-765-489-5499. Autocar's number for this recall is T-1409. Owners may also contact Cummins customer service at 1-812-377-3713.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Cummins was performing the owner notifications for this recall.

Planned Dealer Notification Date : APR 29, 2015 - APR 29, 2015

Planned Owner Notification Date : APR 29, 2015 - APR 29, 2015

* NR - Not Reported