

Part 573 Safety Recall Report**14V-776****Manufacturer Name :** Doubletree RV**Submission Date :** NOV 25,2014**NHTSA Recall No. :** 14V-776**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Doubletree RV
 Address : 1000 Interchange Drive
 PO Box 235 Howe IN 46746
 Company phone : 260-562-1075

Population :

Number of potentially involved : 301
 Estimated percentage with defect : 1

Vehicle Information :

Vehicle : 2006-2013 DRV Select Suite, Tradition, Mobile Suite Estates, Elite Suite

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : TT & FW Models: Select Suite, Tradition, Mobile Suite Estates, Elite Suite

Production Dates : JAN 01, 2006 - APR 25, 2013

VIN (Vehicle Identification Number) Range

Begin : 5KEFA362961002707

End : 5KEFA4337E1006773

 Not sequential VINs**Description of Defect :**

Description of the Defect : If a lock is affected, the key may be able to be removed from the locked door when the key in the deadbolt cylinder is in the horizontal 9 o'clock position, potentially jamming the deadbolt and potentially causing the red lever on the interior side of the lock to become inoperable.

Description of the Safety Risk : In the event the lock became inoperable, a person inside the travel trailer may not be able to unlock and open the main RV door, but he or she could still exit the trailer from the emergency exit.

Description of the Cause : Not identified

Identification of Any Warning that can Occur : None

Supplier Identification :

Component Manufacturer

Name : Fastec Industrial Corp.
Address : 2219 Eddie Williams Rd
 Johnson City TENNESSEE 37601
Country : United States

Chronology :

Compiled by Fastec

Description of Remedy :

Description of Remedy Program : Upon approval of the proposed recall and the recall announcement, DRV, LLC will work with Fastec to notify consumers of the recall. DRV, LLC estimates that it will issue consumer notifications in the fourth quarter of 2013. DRV, LLC will coordinate the recall efforts with Fastec and will refer consumers to Fastec for free replacement of the cylinders in any affected locksets as described more fully in Fastec's Part 573 Report.

How Remedy Component Differs from Recalled Component : Only FIC locks that have an integrated deadbolt are affected by this recall.

Identify How/When Recall Condition was Corrected in Production : Upon receipt of a recall number, DRV will provide the retail list to Fastec for mailing of the approved owner letter.

Recall Schedule :

Description of Recall Schedule : Fastec will be handling this portion of the recall.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported