

GM CUSTOMER CARE AND AFTERSALES
DCS3483
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 17, 2014

Subject: Recall Bulletins 13454C, 14063C, 14092B, 14113D, 14133D
Ignition Switch / Ignition Lock Cylinder / Ignition Key
Part Information and Warranty Transaction Information Sections
Revised

Models: 2005-2010 Chevrolet Cobalt
2006-2011 Chevrolet HHR
2006-2010 Pontiac Solstice
2005-2006 Pontiac Pursuit (Canada Only)
2007-2010 Pontiac G5
2003-2007 Saturn Ion
2007-2010 Saturn Sky

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The Part Information and Warranty Transaction Information sections in the subject bulletins have been revised. This was done to simplify the dealer ordering process for all ignition switch recall parts. Please see the attached bulletins for details and discard all copies of bulletins 13454B, 14063B, 14092A, 14113C and 14133C.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES