

View Message

Sent on 06 12 2014 **Expires on** 06 26 2014
From American Honda Parts, Service & Technical Division, Campaign Administration
Subject Safety Recall: 2005-10 Odyssey Fuel Pump Module Leak PARTS UPDATE

DATE: June 12, 2014

TO: All Honda Sales, Service & Parts Managers and Personnel
FROM: American Honda Parts, Service & Technical Division, Campaign Administration

RE: Safety Recall: 2005-10 Odyssey Fuel Pump Module Leak **PARTS UPDATE**

For dealers experiencing a strong fuel smell from storing the fuel pump sets replaced under service bulletin 14-032: *Safety Recall: Odyssey Fuel Pump*, these fuel sets may be disposed of immediately **in accordance with local regulations**. This only applies to the fuel filter set replaced under this service bulletin 14-032; the published retention policy remains in effect for all other parts.

If you have any questions to this exception or other parts retention issues please contact the WPI Administrative Office at 937-642-2737.

Return Request

You must return all 17048-SHJ-A00 & 17045-SHJ-A30 you have in inventory.

No Shipment Listing or Invoice is required for this return. These returns will not be charged against your SRA credit.

Return iN OAR Procedure

1. Complete the iN OAR procedures.
2. Use Reason Code "S," with eleven zeros for the Shipper Number.
3. Use Item Number "9999."
4. Enter "Ody Fuel Pump/Sending Unit Return" in the Remarks Section.
5. When approved an "Authorization Return document" via the mail will be received. Please return parts as normal with the "Return Authorization attached."
6. Return P/N 17048-SHJ-A00 & P/N 17045-SHJ-A30 on your returning DSO Truck or normal method of return.

After receiving the Authorized Return Documents, ship the parts freight prepaid.

You will be credited return freight charges. **Order adjustment requests (OARs) must be submitted by July 3rd, 2014.**

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.