

GM CUSTOMER CARE AND AFTERSALES  
DCS3206  
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 7, 2014

Subject: 14067 - Safety Recall - Release from Stop Delivery Upon  
Completion of the Recall  
Diesel Fuel Transfer Pump Tube Nut Torque

Models: 2015 Chevrolet Silverado and GMC Sierra HD Chassis Cabs  
Equipped with Dual Fuel Tanks (N2N)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
and Warranty Administrator

General Motors is announcing Safety Recall 14067 today. The total number of U.S. vehicles involved is 51. Please see the attached bulletin for details.

Vehicles involved in this recall were placed on stop delivery February 26, 2014. Once the service procedure contained in the bulletin has been performed on the vehicle, the vehicle is released from stop delivery and can be delivered to the customer.

**Customer Letter Mailing**

The customer letter mail date has not been determined.

**Global Connect (GWM)**

The "Investigate Vehicle History" (IVH) screen will be updated May 9, 2014. A list of involved vehicles in dealer inventory is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

**Campaign Initiation Detail Report (CIDR)**

The CIDR will be available in the near future.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES