

GM CUSTOMER CARE AND AFTERSALES
DCS3184
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 19, 2014

Subject: 14128A – Safety Recall
Incorrect Front Brake Rotor
Customer Letter Added

Models: 2014 Buick LaCrosse and Chevrolet Malibu

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

Bulletin 14128A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 14128.

Customer Letter Mailing

The customer letter mailing will begin on June 20, 2014.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES