

GM CUSTOMER CARE AND AFTERSALES
DCS3789
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 29, 2015

Subject: 13036B – Safety Recall Bulletin
Brake Lamp Malfunction
Revised Service Procedure

Models: 2004-2012 Chevrolet Malibu
2004-2007 Chevrolet Malibu Maxx
2005-2010 Pontiac G6
2007-2010 Saturn AURA

To: All GM Dealers

The bulletin has been revised to update the Service Procedure. Please discard all copies of bulletin 13036A.

GM CUSTOMER CARE AND AFTERSALES