

GM CUSTOMER CARE AND AFTERSALES  
DCS3329  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 29, 2014

Subject: 14356A – Safety Recall  
Inspect Power Steering Hoses  
Revised Inspection Procedure

Models: 2015 Chevrolet Silverado 2500/3500 HD  
2015 GMC Sierra 2500/3500 HD

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
and Warranty Administrator

This bulletin has been revised to include a revised inspection procedure, additional labor operation, and a copy of the customer advisory letter that mailed to customers on 8/15/2014. Please discard all copies of bulletin 14356.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES