

Number <b>14V01</b> Vendor FSA Notice	<b>Certain 2015 F-650/750 Vehicles Equipped with          Cummins Diesel Engines -          Engine Fuel Filter</b>
<b>Date: September 2, 2014</b>	

## This Is a Vendor Field Service Action Notice

Model Year	Model	Assembly Plant	Vehicle Build Date Range
2015	F-650 and F-750 vehicles equipped with an ISB Cummins engine	ESCOBEDO (MEXICO)	Certain vehicles built from May 12, 2014 through August 4, 2014.

### Issue

Cummins Inc. has issued a Safety Recall covering certain Engine Fuel Filters. Cummins determined that the bond that attaches the filter shell to the filter nut plate may fail on affected filters. If this occurs, the shell may separate from the fuel filter nut plate. According to Cummins, the resulting fuel leak can cause the engine to stall without warning and without the ability to restart the engine until the fuel filter has been replaced, increasing the risk of a crash.

### Action

1. On July 31, 2014, Cummins Inc. announced Safety Recall C1545 to replace the Engine Fuel Filter on affected vehicles.
2. Cummins Inc. has contacted all authorized Cummins Service Centers (including Cummins authorized Ford dealers) and provided technical and claiming instructions for replacement of the Engine Fuel Filter.
3. This is a Cummins Safety Recall and Ford has no administrative responsibilities for this recall. **DO NOT SUBMIT CLAIMS FOR THIS REPAIR TO FORD MOTOR COMPANY.**
4. Cummins Inc. will also send all affected owners a letter asking them to have this repair completed by an authorized Cummins Service Center.

### OASIS

OASIS and FSA VIN Lists will be activated on September 2, 2014 to help dealers identify stock and sold vehicles that may be eligible under this program. Because this is a Cummins program, the Open/Closed status in OASIS and the FSA VIN lists will not be updated as vehicles are repaired. As a result, dealers must verify eligibility, based upon Engine Serial Number, with Cummins (800-343-7357) prior to performing repairs.

### PLEASE NOTE

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

<b>Questions?</b>	Cummins Call Center: ..... 1-800-343-7357
-------------------	---