

GM CUSTOMER CARE AND AFTERSALES
DCS3810
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 19, 2015

Subject: 14405B - Safety Recall
Vehicle Hesitation or Stall
Service Procedure Revised

Models: 2004-2007 Cadillac CTS-V
2006-2007 Cadillac STS-V

To: All Cadillac Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

Step 2 of the service procedure has been revised with regard to replacing the fuel level sensor on STS-V vehicles only. This is in addition to replacing the fuel tank fuel pump module and fuel tank jumper harness. Please see the attached bulletin for details and discard all copies of bulletin 14405A.