

**From:** [Broadcast Messaging System](#)  
**To:** [DL-BMS Message Monitors](#)  
**Subject:** Delivery Stop - Side-View Mirror  
**Date:** Thursday, October 09, 2014 2:00:09 PM

Publish Date: October 09, 2014  
From: Technical Service  
Expiration Date: October 23, 2014

DCSnet Message  
**Urgent**



**Subject: Delivery Stop - Side-View Mirror**

A Delivery Stop has been issued on certain 2014 model year F25 and F26 vehicles. These vehicles may be equipped with an incorrect side-view mirror.

VINs affected:

0K32981, 0D50140, 0D50148, 0D50162, 0E96258, 0F89125, 0F89132, 0K32986

Service Information Bulletin B51 29 14 will be published with further information regarding this Campaign.

Thank you, Eugene Aton, Technical Service

**Attachments:**  
No Attachments No Attachments

**Recipients:** All, 96255, All Departments, All Personnel  
All, 43764, All Departments, All Personnel  
All, 40800, All Departments, All Personnel  
All, 36721, All Departments, All Personnel

