

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Delivery Stop - Seat Frame
Date: Friday, October 10, 2014 11:42:06 AM

Publish Date: October 10, 2014
From: Technical Service
Expiration Date: October 24, 2014

DCSnet Message
Urgent



Subject: **Delivery Stop - Seat Frame**

A Delivery Stop has been issued on certain F15 vehicles. These vehicles may need the left rear seat frame replaced.

VINs affected: 0K57285, 0K57265, 0H35672

A Service Information bulletin will be published with further information regarding this Campaign.

Thank you, Eugene Aton, Technical Service

Attachments:

No Attachments No Attachments

Recipients: BMW SAV (Light Trucks), 46038, All Departments, All Personnel
BMW SAV (Light Trucks), 36752, All Departments, All Personnel
BMW SAV (Light Trucks), 26747, All Departments, All Personnel

