

[Next Unread Message](#)[View Message](#)

Sent on 11 06 2014 Expires on 11 21 2014
From Motorcycle Communications and Training
Subject Safety Recall Service Bulletins Published: 2014 NSS300/A and 2014 Grom125



Communications and Training

November 6, 2014

Safety Recall Service Bulletins Published: 2014 NSS300/A and 2014 Grom125

Dear Honda Powersports Dealer:

Service Bulletins for the above named models affected by a Safety and Emissions Recall are now available on ***IN***. To view the bulletins click on the links below.

[SAFETY RECALL: 2014 Grom125 - Fuel Pump Replacement \(Grom125 #1\)](#)

[SAFETY RECALL: 2014 NSS300/A - Fuel Pump Replacement \(NSS300 #1\)](#)

Please make sure all departments in your dealership are aware of this action.

Sincerely,
American Honda Motor Co., Inc.

William Hanson
Manager
Communications and Training
Motorcycle Division

Bulletin Number: 14-0365

[▲ BACK TO TOP](#)

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.