



*MAZDA DEALER EMAIL*

*zoom-zoom*

*zoom-zoom*

*zoom-zoom*

November 10, 2014

Attention: Mazda Sales and Service Managers

Subject: Repair Procedure Update for Recall 8014J – 2014-2015 Mazda6 TPMS

The repair procedure for Recall 8014J has been updated to include TPMS reset instructions after ABS module reprogramming.

Your understanding and support in carrying out this campaign are greatly appreciated.

Mazda Technical Services