

GM CUSTOMER CARE AND AFTERSALES  
DCS3501  
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 15, 2015

Subject: 14892 - Safety Recall – Rear Axle Shaft Not Properly Heat Treated

Models: 2015 Chevrolet Silverado 1500  
2015 GMC Sierra 1500

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
and Warranty Administrator

This message is an **IMPORTANT REMINDER** to complete the repairs outlined in bulletin 14892, sent to dealers on December 16, 2014. It is mandatory to complete these steps before the vehicle is sold. A copy of the bulletin is attached to this message for your convenience.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES