

February 24, 2014

IMPORTANT SAFETY RECALL

Subject: Safety Recall **1213G**
Model 587 Loose Door Pull Handles
NHTSA 14V-015
Expiration Date: None
Affected VINs are shown on the opposite side of this page

1213G - 1US

L & L LEASING CORP.
69 FITCHBURG RD.
AYER, MA 01432-1003

215124-1213G

Dear Peterbilt Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect that relates to motor vehicle safety exists in certain Model 587 vehicles manufactured between May 8, 2012 and November 19, 2013. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

The door pull portion of the door pad assembly may separate from the door when used if the fasteners are insufficiently tightened. If an occupant is using the door pull to assist in getting in or out of the vehicle, the sudden detachment of the pull handle may result in a fall, increasing the risk of injury.

The problem is...	Loose door pull handles
What your dealer will do...	Tighten door pull fasteners
What you must do ...	Contact your dealer immediately to schedule an appointment

Peterbilt has initiated a recall to tighten the screws that hold the door pull brackets to the door structure in your truck. Please contact your Peterbilt dealer immediately to schedule an appointment for this repair. To find your nearest Peterbilt dealer, please visit Dealer Locator at www.Peterbilt.com. This repair should take approximately one hour, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook Street, Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.


If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood
Director Quality Services