



IMPORTANT SAFETY RECALL

July 2014

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that certain 2014 model year Chevrolet Malibu vehicles equipped with a 2.5L engine and Auto Stop/Start fail to conform to Federal/Canada Motor Vehicle Safety Standard, 135, *Light Vehicle Brake Systems*. As a result, GM is conducting a recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- This notice applies to your vehicle VIN: _____.
- Your vehicle is involved in GM safety recall 14201.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

If your vehicle experiences a complete loss of brake vacuum assist, the hydraulic boost assist (HBA) can be disabled, causing a noncompliance with the requirements of Section 7.11, *Brake Power Assist Unit Inoperative*. A disabled HBA will cause a DIC 'Service Brake Assist' and 'Check Engine' light to be illuminated, and increased brake pedal effort and stopping distance will be required, increasing the risk of a crash.

What will we do?

Your GM dealer will reprogram your vehicle's electronic brake control module. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 20 minutes.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

If the "Service Brake Assist" message and Check Engine Light are illuminated, the pedal may require greater effort and greater distance may be needed to stop.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	1-800-833-2438
Guam	65-6267-1752	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 14V247.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jim Moloney
General Director,
Customer and Relationship Services

GM Recall #14201