

***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. (TBA)

August 7, 2014

Mr. Kerry Legg
711 Kernaghan Avenue
Winnipeg, Manitoba R2C 3T4

Mr. David Warren
106 National Drive
Anniston, AL 36207

Dear Kerry and David:

We are writing to inform you that Cummins Inc. has determined that a safety-related defect exists in Fleetguard UFF-XT fuel filters, part number FF63009, manufactured between April 25, 2014 and June 29, 2014 and having a date code between 14115 and 14180. Cummins has initiated a recall of the subject filters, as well as certain ISB and ISL engines equipped with these filters. Our records indicate that some of these engines have been shipped to your companies (100 to NABI, 176 to New Flyer).

A copy of Cummins' Part 573 Defect Notification letter is enclosed. This notification has been submitted to the National Highway Traffic Safety Administration (NHTSA).

Enclosed is a list of Engine Serial Numbers for affected engines shipped to your plants. For engines installed in vehicles that have left your control, we encourage you to make a safety defect determination in accordance with 49 USC 30118 *et seq.* and, as appropriate, to submit a Defect Notification to NHTSA in accordance with 49 CFR Part 573. Cummins will conduct the recall, including notifying owners pursuant to 49 C.F.R. Part 577, performing the remedy, and submitting quarterly status reports to NHTSA. To facilitate owner notification work has already begun with your teams to provide customer contact and VIN information to your Cummins account team leader. Please work with your Cummins account team leader to ensure contact information is provided as quickly as possible.

For engines/vehicles that are still in your inventory, please contact the Customer Quality Assurance representative at the Cummins engine plant that supplied the engines to arrange for repairs. Engines are to be repaired under Cummins Campaign C1545. It is illegal to deliver these engines, or vehicles equipped with these engines, under a sale or lease until this condition has been remedied.

Cummins apologizes for this inconvenience, but we are initiating this action in the interest of our customers' safety and satisfaction with our products.

Please confirm receipt of this communication.

Sincerely,



Enclosures: Cummins Part 573 Defect Notification
List of Engine Serial Numbers