

October 3, 2014

DEFECT INFORMATION REPORT

This supplements Toyota's Part 573 Report of September 18, 2014 concerning the fuel delivery pipe issue on certain Toyota Avalon, Camry, Sienna, Highlander and Lexus RX vehicles

The involved vehicle VIN range and corresponding number of affected vehicles is revised below:

Identification of Involved Vehicles:

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period
			VDS	VIS	
Toyota/ Avalon	2014	TMMK	BK1EB	EU110653 - EU125406	April 29, 2014 through July 24, 2014
Toyota/ Camry	2014		BK1FK	EU026612 - EU026761 EU549606 - EU550234	April 29, 2014 through May 22, 2014
Toyota/ Sienna	2014	TMMI	*K3DC	ES086259 - ES091952 ES485198 - ES515703	April 30, 2014 through July 31, 2014
Toyota/ Highlander	2014		*KRFH	ES024288 - ES031773 ES043192 - ES066173	April 30, 2014 through July 25, 2014
Lexus/ RX350	2015	TMMC	*K1BA	FC153769 - FC158529 FC259020 - FC266531	May 1, 2014 through June 12, 2014

Note: Although the involved vehicles are within the above VIN range, not all vehicles in this range were sold in the U.S. Only vehicles equipped with 2GR-FE engines containing the fuel delivery pipe produced by FPI are involved. No other Toyota or Lexus vehicles use the same fuel delivery pipe as the subject vehicles.

Total Number of Vehicles Involved:

Toyota Avalon	:	2,325
Toyota Camry	:	568
Toyota Sienna	:	4,715
Toyota Highlander	:	4,982
Lexus RX350	:	3,282
Total:		15,872