



PORSCHE

December 23, 2014
VIA NHTSA Recall Portal

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Avenue, S.E.
Washington, D.C. 20590

Porsche Cars North America, Inc.
980 Hammond Drive
Suite 1000
Atlanta, Georgia 30328
(770) 290-3500 Fax: (770) 290-3700

Subject: Notification of Voluntary Recall
2015 Porsche Cayenne
Alignment of Suspension

Dear Ms. Lewis:

Porsche Cars North America, Inc. ("Porsche"), on behalf of Dr. Ing. h.c. F. Porsche AG ("Porsche AG"), hereby informs you of Porsche's intention to conduct a voluntary safety related recall and remedy campaign involving the 2015 Porsche Cayenne. This information is submitted in accordance with the provisions of Part 573 of Title 49 of the code of Federal Regulations.

573.6 (c) (1) Manufacturer's Name
Dr. Ing. h.c. F. Porsche AG
70435 Stuttgart
Germany

Importer / Agent
Vice President, General Counsel and Secretary
Porsche Cars North America, Inc.
980 Hammond Drive
Suite 1000
Atlanta, GA 30328

573.6 (c) (2) Identification of Vehicles

Make: Porsche

Model Year: 2015

Models: Cayenne Diesel
Cayenne S

Production Dates: November 26, 2014 to November 27, 2014
VIN Ranges: WP1AF2A22FLA35353 and WP1AB2A23FLA58765
Vehicle Type: Multipurpose Passenger Vehicle
Bodystyle: 5-door SUV
Component Supplier: No applicable

573.6 (c) (3) Number of Vehicles Potentially Containing the Defect

2

573.6 (c) (4) Percentage of Vehicles Actually Containing Defect

100%

573.6 (c) (5) Description of Defect

There is the possibility that the suspension alignment on the front and rear axles have not been performed correctly and, the screw connections of the camber, toe and caster have not been tightened with the specified torque due to a manufacturing error. Vehicle handling could be affected.

573.6 (c) (6) Basis for Determination

To be determined.

573.6 (c) (7) Noncompliance Test Result

Not applicable.

573.6 (c) (8) Proposed Remedial Program

The affected vehicles will be recalled to the workshop and have a front and rear suspension alignment performed and all screw connections of the camber, tow and caster re-tightened with the specified torque.

573.6 (c) (9) Remedy Proposal for the Replacement of Tires

Not applicable.

573.6 (c) (10) Recall Communications


A representative copy of all bulletins and other communications sent to dealers and owners will be submitted within five (5) days of dealer/owner notification.

573.6 (c) (11) Manufacturer Campaign Number

AF04.

Should you have any questions or require further information, please do not hesitate to contact me at (770) 290-3627.

Sincerely,

A handwritten signature in black ink, appearing to read 'Walter J. Lewis', written over a light blue horizontal line.

Walter J. Lewis, Manager
Regulatory Affairs