

SAFETY ADVISORY # 14-216

Hideout 308BHDS GFCI

Keystone RV Company is conducting a voluntary RECALL notification campaign in accordance with the National Traffic and Motor Vehicle Safety Act. It has been decided the 120V receptacle in the exterior kitchen may not be on GFCI protected circuit. If this condition exists it will lead to an increased risk of electrical shock if an electrical fault exists with an appliance plugged into the receptacle. Verify the outside kitchen receptacle is on a GFCI circuit and if not, replace the receptacle with a GFCI type.

Models include: 2014 Hideout 308BHDS Travel Trailers
 2015 Hideout 308BHDS Travel Trailers

Serial Number Ranges: 2014 Hideout E7203118 - E7205630
 2015 Hideout F7200195 - F7203011

Parts Required: Refer to Step 1 to determine if part is required
 KRV # 353649 -- Recept - GFI - 15A120V - Black - w/Plate

Tools Required: - Multimeter - Screw Gun - Wire Pliers

REPAIR INSTRUCTIONS

ONE: **INSPECT GFCI**

Step 1 Locate the GFCI receptacle in the exterior kitchen next to the sink and verify 120V power to it. Test for proper protection; trip the GFCI in the front bathroom and verify power to the 120V receptacle in the outside kitchen is shut off. If power remains on, the exterior kitchen receptacle must be replaced by a GFCI protected type.



TWO: WARRANTY REIMBURSEMENT

INSPECTION ONLY

Submit the claim on Key Express using **Flat Rate Code # 7121619F** and **Safety Advisory # 14-216** noted in the customer complaint section. The amount of time authorized for inspection only is 0.3 hours.

INSPECT AND REPLACE

Submit a pre-authorization request on Key Express using **Flat Rate Code # 7121619B** with **Safety Advisory # 14-216** noted in the customer complaint section of the form. The amount of time authorized for this repair is 0.7 hours.

Please call Keystone RV Customer Service if you have any questions:

Hideout **(866) 273-1454**