

**SAFETY ADVISORY # 14-218****Rubicon Generator Fuel Line Clamp**

Keystone RV Company is conducting a voluntary RECALL notification campaign in accordance with the National Traffic and Motor Vehicle Safety Act. It has been decided the vehicles subject to this recall campaign may not have the clamp installed correctly at the generator fuel filter and fuel tank. If the fuel line becomes disconnected it increases the risk of a fuel leak leading to an increased risk of fire, personal injury and property damage. This advisory explains how to correct the problem.

**Model and Serial Numbers Included:**

2015 Rubicon Travel Trailers

Serial Number Range: FH985207 - FH985246


**Parts Required per Unit:** None**Tools Required:** Slotted Screwdriver**ONE      INSPECTION and REPAIR****Step 1**      Locate the trailer on a level, flat and hard surface. Chock the wheels.**Step 2**      Look under the generator and inspect the incoming fuel line and clamp to the generator where the line attaches to the fuel filter. Verify the fuel line is fully engaged on the barb fitting and the clamp is in the proper position and it is tight. See Figure 1 & 2.**Figure 1 - Incorrect****Figure 2 – Correct****Step 3**      Look at the fuel pickup line on the fuel tank. Verify the fuel line is fully engaged on the barb fitting and the clamp is in the proper position and it is tight. See Figure 3 & 4.



Figure 3 - Incorrect



Figure 4 – Correct

**TWO**      **WARRANTY REIMBURSEMENT**

Submit the request on Key Express using **Flat Rate Code # 7221842A** with **Safety Advisory #14-218** noted in the customer complaint section. The time authorized for this repair is **0.5 hours**.

If you have any questions, please call Customer Service at **(855) 382 - 4100**.