

**IMPORTANT: SAFETY RECALL NOTICE
PLEASE OPEN IMMEDIATELY**

PLEASE DELIVER TO REGISTERED OWNER

VEHICLE
IDENTIFICATION ► XXXXXXXXXXXXXXXXXXXX JE2
NUMBER



JE2

*****AUTO**MIXED AADC 926





AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

June 2015

RE: 2014 Odyssey
NHTSA Recall 14V-175

IMPORTANT

- **Your vehicle is included in a safety recall and should have the recall service done as soon as possible.**
- **Any authorized Honda dealer will perform the recall service at no charge to you.**

Dear Honda Odyssey Owner:

What is the reason for this notice?

Our records indicate that a SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. There is a possibility that the electrical coupler for the side curtain airbag on the passenger side may have been damaged during manufacturing. Damage to the electrical coupler could cause the SRS warning light to illuminate as well as prevent the side curtain airbag from deploying during a crash, increasing the risk of injury.

What should you do?

Please contact any authorized Honda dealer to schedule a service appointment. The dealer will repair the side curtain airbag electrical coupler on the passenger side. This work will be done *free of charge*.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 1-888-234-2138. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this safety recall may cause you. We are taking this action in the interest of your safety and continued satisfaction with your Honda vehicle.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #14-020

JE2