Recall Quarterly Report

15V-098

Manufacturer Name : Toyota Motor Engineering & Manufacturing NHTSA Recall No. / MFR Recall No. : 15V-098 / Recall Subject : Improperly Tightened Rear Axle Bolts Owner Notification Beginning Date : APR 03, 2015 Owner Notification End Date: APR 03, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 27, 2016	2015-4	226	214	0	0
2	OCT 30, 2015	2015-3	226	193	0	0
1	JUL 27, 2015	2015-2	226	169	0	0

This Document Last Updated : JAN 27, 2016

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.