

**Recall Quarterly Report****15V-098****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**NHTSA Recall No. / MFR Recall No. :** 15V-098 /**Recall Subject :** Improperly Tightened Rear Axle Bolts**Owner Notification Beginning Date :** APR 03, 2015**Owner Notification End Date:** APR 03, 2015

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JUL 28, 2016	2016-2	226	203	9	0
4	APR 27, 2016	2016-1	226	220	0	0
3	JAN 27, 2016	2015-4	226	214	0	0
2	OCT 30, 2015	2015-3	226	193	0	0
1	JUL 27, 2015	2015-2	226	169	0	0

This Document Last Updated : AUG 05, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.