

**Recall Quarterly Report****15V-221**

**Manufacturer Name :** Yamaha Motor Corporation, USA  
**NHTSA Recall No. / MFR Recall No. :** 15V-221 /990095  
**Recall Subject :** Shock Absorber Damping Rod Nut may Loosen/Detach  
**Owner Notification Beginning Date :** APR 29, 2015  
**Owner Notification End Date:** MAY 04, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	OCT 14, 2016	2016-3	350	332	0	0
5	JUL 05, 2016	2016-2	350	330	0	0
4	APR 07, 2016	2016-1	350	322	0	0
3	JAN 04, 2016	2015-4	350	311	0	0
2	NOV 16, 2015	2015-3	350	304	0	0
1	AUG 26, 2015	2015-2	350	297	0	0

This Document Last Updated : OCT 25, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.