

Recall Quarterly Report**15V-261****Manufacturer Name :** Mercedes-Benz USA, LLC - DBA Sprinter**NHTSA Recall No. / MFR Recall No. :** 15V-261 /**Recall Subject :** Oil may Leak from Chain Tensioner Gasket**Owner Notification Beginning Date :** MAY 18, 2015**Owner Notification End Date:** MAY 18, 2015

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 28, 2016	2015-4	1,335	852	0	0
2	OCT 27, 2015	2015-3	1,335	615	0	0
1	JUL 20, 2015	2015-2	1,335	394	0	0

This Document Last Updated : FEB 08, 2016

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.