

**Recall Quarterly Report****15V-268**

**Manufacturer Name :** Ducati North America  
**NHTSA Recall No. / MFR Recall No. :** 15V-268 /RCL-15-002  
**Recall Subject :** Shock Absorber Damping Rod Nut may Loosen/Detach  
**Owner Notification Beginning Date :** JUN 29, 2015  
**Owner Notification End Date:** JUN 29, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	APR 27, 2016	2016-1	549	318	28	0
3	JAN 08, 2016	2015-4	549	284	27	0
2	OCT 22, 2015	2015-3	549	228	27	0
1	JUL 28, 2015	2015-2	549	35	8	0

This Document Last Updated : MAY 18, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.