## **Recall Quarterly Report**

15V-284

Manufacturer Name : Toyota Motor Engineering & Manufacturing NHTSA Recall No. / MFR Recall No. : 15V-284 / Recall Subject : Driver Side Frontal Air Bag May Rupture Owner Notification Beginning Date : AUG 21, 2015 Owner Notification End Date: AUG 21, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	JAN 26, 2017	2016-4	159,700	86,700	6,815	0
5	OCT 27, 2016	2016-3	159,700	78,963	0	0
4	JUL 28, 2016	2016-2	159,700	68,185	6,807	0
3	APR 27, 2016	2016-1	159,700	58,414	6,774	0
2	JAN 27, 2016	2015-4	159,700	41,875	0	0
1	OCT 30, 2015	2015-3	159,700	7,835	0	0

This Document Last Updated : FEB 01, 2017

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7