

**Recall Quarterly Report****15V-286****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**NHTSA Recall No. / MFR Recall No. :** 15V-286 /14491**Recall Subject :** Passenger Side Front Air Bag Inflator may Rupture**Owner Notification Beginning Date :** JUL 13, 2015**Owner Notification End Date:** JUL 13, 2015

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
7	APR 20, 2017	2017-1	1,069,055	493,287	0	0
6	JAN 26, 2017	2016-4	1,069,055	471,367	0	0
5	OCT 27, 2016	2016-3	1,069,055	455,465	44,983	0
4	JUL 26, 2016	2016-2	1,069,055	419,187	44,982	0
3	APR 27, 2016	2016-1	1,069,055	356,380	44,937	0
2	JAN 27, 2016	2015-4	1,069,055	313,095	1,109	0
1	OCT 30, 2015	2015-3	1,069,055	260,842	1,270	0

This Document Last Updated : APR 28, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.