

Recall Quarterly Report**15V-351**

Manufacturer Name : Mercedes-Benz USA, LLC.
NHTSA Recall No. / MFR Recall No. : 15V-351 /2015050005
Recall Subject : Oil may Leak from Chain Tensioner Gasket
Owner Notification Beginning Date : JUN 23, 2015
Owner Notification End Date: JUN 23, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	OCT 11, 2016	2016-3	814	752	0	0
5	JUL 28, 2016	2016-2	814	740	0	0
4	APR 07, 2016	2016-1	814	696	0	0
3	JAN 22, 2016	2015-4	814	646	0	0
2	OCT 14, 2015	2015-3	814	514	0	0
1	JUL 29, 2015	2015-2	814	167	0	0

This Document Last Updated : OCT 18, 2016

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.