

**Recall Quarterly Report****15V-355**

**Manufacturer Name :** Vermeer Manufacturing Company  
**NHTSA Recall No. / MFR Recall No. :** 15V-355 /IK3175  
**Recall Subject :** Hitch Safety Chain may be Incorrectly Installed  
**Owner Notification Beginning Date :** JUL 14, 2015  
**Owner Notification End Date:** JUL 14, 2015



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2        | JAN 14, 2016    | 2015-4         | 64                | 23             | 0                 | 0             |
| 1        | OCT 07, 2015    | 2015-3         | 64                | 22             | 0                 | 0             |

This Document Last Updated : FEB 08, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.