

**Recall Quarterly Report****15V-537**

**Manufacturer Name :** BMW of North America, LLC  
**NHTSA Recall No. / MFR Recall No. :** 15V-537 /  
**Recall Subject :** Engine Control Unit Software may cause Low Idle  
**Owner Notification Beginning Date :** OCT 14, 2015  
**Owner Notification End Date:** OCT 14, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 25, 2016	2016-3	1,060	683	0	0
3	JUL 26, 2016	2016-2	1,060	626	0	0
2	APR 06, 2016	2016-1	1,060	510	0	0
1	JAN 27, 2016	2015-4	1,060	412	0	0

This Document Last Updated : NOV 08, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.