

**Recall Quarterly Report****15V-558**

**Manufacturer Name :** General Motors LLC  
**NHTSA Recall No. / MFR Recall No. :** 15V-558 /15299  
**Recall Subject :** Rear Defogger Coil Antenna Module may Overheat  
**Owner Notification Beginning Date :** OCT 16, 2015  
**Owner Notification End Date:** OCT 16, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 17, 2016	2016-3	96,145	92,394	0	0
3	JUL 29, 2016	2016-2	96,145	89,247	0	0
2	APR 27, 2016	2016-1	96,145	83,386	1	0
1	JAN 29, 2016	2015-4	96,145	65,526	0	0

This Document Last Updated : OCT 17, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.