

**Recall Quarterly Report****15V-656****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**NHTSA Recall No. / MFR Recall No. :** 15V-656 /F0T**Recall Subject :** Driver's Knee Air Bag Module Bolts may Loosen**Owner Notification Beginning Date :** NOV 19, 2015**Owner Notification End Date:** NOV 19, 2015

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 20, 2017	2017-1	306	254	13	0
5	JAN 26, 2017	2016-4	306	247	13	0
4	OCT 27, 2016	2016-3	306	230	13	0
3	JUL 26, 2016	2016-2	306	211	13	0
2	APR 27, 2016	2016-1	306	173	13	0
1	JAN 27, 2016	2015-4	306	90	0	0

This Document Last Updated : APR 28, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.