## **Recall Quarterly Report**

15V-674

**Manufacturer Name:** Mazda North American Operations **NHTSA Recall No.** / **MFR Recall No.**: 15V-674 /8715J

**Recall Subject:** Ignition Switch may Overheat

**Owner Notification Beginning Date :** DEC 17, 2015

**Owner Notification End Date:** DEC 21, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JAN 30, 2017	2016-4	1,368,500	8,045	365,041	19,498
4	OCT 30, 2016	2016-3	1,368,500	7,528	364,951	19,338
3	JUL 27, 2016	2016-2	1,368,500	6,296	362,752	19,056
2	APR 27, 2016	2016-1	1,368,500	1,470	198,796	17,307
1	JAN 24, 2016	2015-4	1,368,500	0	0	15,617

This Document Last Updated: FEB 01, 2017

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.