

Recall Quarterly Report**15V-709**

Manufacturer Name : Mercedes-Benz USA, LLC.
NHTSA Recall No. / MFR Recall No. : 15V-709 /MFR ID Code
Recall Subject : Rear Drive Shaft may Loosen and Separate
Owner Notification Beginning Date : NOV 09, 2015
Owner Notification End Date: NOV 09, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 28, 2017	2017-1	52	36	0	0
5	JAN 10, 2017	2016-4	52	33	0	0
4	OCT 11, 2016	2016-3	52	31	0	0
3	JUL 28, 2016	2016-2	52	29	0	0
2	APR 07, 2016	2016-1	52	20	0	0
1	JAN 22, 2016	2015-4	52	18	0	0

This Document Last Updated : MAY 08, 2017

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.