

Recall Quarterly Report**15V-782**

Manufacturer Name : BMW of North America, LLC
NHTSA Recall No. / MFR Recall No. : 15V-782 /
Recall Subject : Driveshaft Slip-Joint may not have been Greased
Owner Notification Beginning Date : JAN 14, 2016
Owner Notification End Date: JAN 14, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 27, 2017	2016-4	42	40	1	0
3	OCT 25, 2016	2016-3	42	40	1	0
2	JUL 27, 2016	2016-2	42	39	1	0
1	APR 25, 2016	2016-1	42	37	1	0

This Document Last Updated : FEB 10, 2017

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.