

Recall Quarterly Report**15V-794**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 15V-794 /WQV-57
Recall Subject : Drive Shaft May Detach From Differential
Owner Notification Beginning Date : DEC 10, 2015
Owner Notification End Date: DEC 10, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 12, 2017	2017-1	3,251	3,200	4	0
5	JAN 23, 2017	2016-4	3,251	3,194	4	0
4	OCT 11, 2016	2016-3	3,251	3,182	4	0
3	JUL 18, 2016	2016-2	3,251	3,163	4	0
2	APR 12, 2016	2016-1	3,251	3,094	4	0
1	JAN 13, 2016	2015-4	3,251	2,906	3	0

This Document Last Updated : MAY 08, 2017

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.