

**Recall Quarterly Report****15V-794****Manufacturer Name :** Subaru of America, Inc.**NHTSA Recall No. / MFR Recall No. :** 15V-794 /WQV-57**Recall Subject :** Drive Shaft May Detach From Differential**Owner Notification Beginning Date :** DEC 10, 2015**Owner Notification End Date:** DEC 10, 2015

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 12, 2016	2016-1	3,251	3,094	4	0
1	JAN 13, 2016	2015-4	3,251	2,906	3	0

This Document Last Updated : APR 12, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.